105 Load R4, [R30]
110 Add R5, (R32+R31)
115 Add R6, (R29+R5)
120 Load R10, (R4)

FIG. 1A (Prior Art)




FIG. 1B (Prior Art)




FIG. 2




FIG. 3




FIG. 4

	505 510	515		520
R#_/	SDS S10 Data	State	Instruction Address	
	/	/		1
0		00		
1		00		
2		00		
3		00		
4	xxxxxxxxxxxxx	01	ууууууууууу	
5		00		
6		00		
7		00		
8		00		
9		00		

500

FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9